4 CRUDE MAJOR EWO NO. :	BE301-E2	REV: 1
PLANT: 4 CRUDE	SAP COST CENTER:	DD173-EXP
W/O # 313119-001	PROJECT / OUTAGE	C#: SDD108A
C-1100 PED INSTRUCTIONS		
MOC#:		
Level 1 - Management of Change Review Will This Change: Cause the use of different feeds, chemicals, or catalysts? Cause the use of different process conditions, instrumentation, process control, or affect upstream/downstream plants? Cause the use of new or modified equipment (which is other than in-kind)? Alter equipment siting, building, trailer locations, roads, or fire protection? Require modifying existing and/or developing new procedures? Affect employee emergency response due to an organizational change? Transfer the responsibility for any environmental, health, or safety-related task? Alter the permanent staffing level or organization of any safety-sensitive job?		
SAFETY OPERATOR IN VOC S	ERVICE? IN PLANT WELDING?	
X Yes No Yes	□ No □	Yes X No
APPROVALS		
OPERATIONS: K. Sohnrey	DATE: 3/23/11	PHONE: 2-2042
ENGINERRING: B. Purvis B.	DATE: 3/22/11	PHONE: 2-2853
IMPACT. T.L: M. Greenfield	DATE: 3/22/11	PHONE: 2-1179
MAINTENANCE: V. Massaro Vf Muyrus	DATE: 3/22/11	PHONE: 2-5995
Remove Reference to Internal Overflash Meter Work R. RAMIREZ MAR 21 2011		

1.0 SCOPE

Enter C-1100 for cleaning, inspection, and small repairs.

2.0 GENERAL REQUIREMENTS

Clean column per Process Engineering (PED) and injection requirements.

3.0 MATERIALS


None

4.0 WORK DESCRIPTION

- 4.1 Enter column. Remove manways for access to all trays.
- 4.2 Allow PED and inspection to perform a dirty inspection of the column immediately after opening.
- 4.3 Clean any sludge or scale that has accumulated on the trays or in the draw boxes.
- 4.4 Allow PED and Designs Engineering (DED) to inspect the flash zone impingement plate, the downcomer in tray 33, the sump on tray 26, and the sump on tray 6. Make any needed repairs as determined by engineering.
- 4.5 PED, DED, and Inspection must inspect and sign off for final closure.
- 4.6 After final sign-off, close all manways.

5.0 ATTACHMENTS

5.1 C-1100 Column drawing.



Short Inf 2